Photos taken during site visit on 24th August 2010 at Malana by Prakash Bhandari

Destruction of forest due to muck disposal above power house of Malana-II HEP

Destruction caused by construction and unscietific dumping of muck and dense conifer forest

LAnslides caused in Malana villages due to vibrations caused by blasting for road construction

Malana stream and vegetation to be dried up once Malana-II HEP is commissioned

Power transmission line of Malana-II HEP & within 20 meters diversion weir of Malana-I leaving no water flow on natural course

Community toilets without water supply

Poor Condition of hospital which EPPL has claimed it will improve

Fodder for sustenance of livestock acitvity and the bad conditios of paths